Collins Divisions
Cedar Rapids, Iowa 52498
(319) 395-1000
Cable COLINRAD Cedar Rapids
October 1, 1982



CHANGE 1 TO KWM-380/HF-380 SERVICE BULLETIN NO 9

Attached is a revised issue of KWM-380/HF-380 Service Bulletin No 9 titled, "Stop PA Oscillations and Adjust Circuit Gain," dated 2 January 1981.

This revision makes the following changes:

- 1. Page 1, serial number effectivity table: TBD is replaced by serial numbers.
- 2. Pages 9/10: Figure 1, sheet 3, was revised to show the correct circuit connections of transformers A1A1T2 and A1A1T3.

Black bars in the margin indicate the location of the changes. This revised issue replaces the entire original publication.



350510

KWM-380 TRANSCEIVER (622-5093-001, -101)
HF-380 TRANSCEIVER (622-3580-001, -101)
POWER AMPLIFIER/HEAT SINK ASSEMBLY A1 (634-8481-003)
POWER AMPLIFIER CIRCUIT CARD ASSEMBLY A1A1 (638-6775-001)

SERVICE BULLETIN NO 9

STOP PA OSCILLATIONS AND ADJUST CIRCUIT GAIN

This service bulletin applies to the following:

EQUIPMENT	APPLICABLE TO SERIAL NUMBER	PRODUCTION CUT-IN SERIAL NUMBER
KWM-380		
622-5093-001, -101		
634-8481-003	500 and below, 508	501 through 507, 509 and above
638-6775-001	484 and below, 486 through 489, 491, 498, and 500	485, 490, 492 through 497, 499, 501 and above
HF-380		
622-3580-001, -101		1
634-8481-003	35 and below, 37, 38, 39, 41, 42, and 44	36, 40, 43, 45 and above
638-6775-001	50 and below, 52	51, 53 and above

Production cut-in for power amplifier assembly A1 (634-8481-003) is REV G. Production cut-in for power amplifier circuit card assembly A1A1 (638-6775-001) is REV N.

The purpose of this service bulletin is as follows:

- 1. Power amplifier oscillations at 0.5 MHz are stopped by adding feedback. The oscillations can be detected by observing higher than normal reflected power when transmitting into an antenna on 21- or 28-MHz bands.
- 2. Power amplifier oscillations at miscellaneous frequencies, due to high vswr, are stopped by making miscellaneous component changes.

3. Circuit gain can vary due to transistor parameter variations between vendors. This problem is solved by selecting the value of resistor R7 to match the selected vendor for Q41 at time of installation.

Estimated time required is 4.0 man-hours.

The modification parts are itemized in the material information paragraph. For information concerning parts, contact Collins Service Center, Rockwell International, 6001 Threadgill Avenue, El Paso, Texas 79924. Reference KWM-380/HF-380 Service Bulletin No 9 in all correspondence.

No special tools or equipment are required.

This service bulletin references the KWM-380, CPN 523-0769878, and HF-380, CPN 523-0769880, service manuals.

MODIFICATION PROCEDURE

- A. Turn off all power to the transceiver.
- B. Remove the dust cover by removing the four screws located adjacent to the four feet on the bottom of the transceiver.
- C. Remove power amplifier/heat sink assembly A1 by removing three screws on each side of the heat sink. Refer to the service manual overall unit section, figure 7.
- D. Remove the metal cover from power amplifier circuit card assembly A1A1. Refer to the service manual chassis/power supply A9 and front panel A10 section, figure 3, item 1.
 - NOTE: Do not remove circuit card A1A1 from power amplifier/heat sink assembly A1. Refer to figure 1 while performing steps E through T. Refer to figure 2 for a schematic diagram of the latest configuration.
- E. Remove 1500-pF capacitor C55 by cutting the leads close to the body of the component. Leave the capacitor leads soldered into the circuit card.
- F. Install a 1000-pF capacitor (912-3315-000), connecting the leads to the leads of the capacitor removed in step E.
- G. Install a $2.7-\mu H$ coil L44 (240-2715-180) as shown in figure 1, detail A.
- H. Remove 0.27- μ H inductors L23 and L24 by cutting the leads close to the component body. Leave the inductor leads soldered into the circuit card.
- I. Install two 3.3- μ H inductors (240-2029-000), connecting the leads to the leads of the inductors removed in step H.
- J. Install $100-\Omega$ resistor R123 (745-1310-000) in parallel with L23. Wrap the resistor leads around the coil leads and solder.


- K. Install $100-\Omega$ resistor R124 (745-1310-000) in parallel with L24. Wrap the resistor leads around the coil leads and solder.
- L. Examine transistors Q41A/B and resistor R7. If Q41 was manufactured by Motorola, the value of R7 should be 15 Ω . If Q41 was manufactured by CTC, the value of R7 should be 27 Ω . If it is necessary to replace R7, cut the resistor leads close to component body, leaving the leads soldered into the circuit card. Install the new resistor (15 Ω , 745-0683-000, or 27 Ω , 745-0692-000), attaching the leads to the old resistor leads.
- M. Install a wire (421-2020-000) in parallel with resistor R23. Wrap the ends of the wire around the R23 leads and solder.
- N. Install a wire (421-2020-000) in parallel with resistor R24. Wrap the ends of the wire around the R24 leads and solder.
- O. Remove 40.2-k Ω resistor R93 by cutting the leads close to the body of the component. Leave the leads soldered into the circuit card.
- P. Install a 44.2-k Ω resistor (705-1075-000) attaching the leads to the leads of the resistor removed in step O.
- Q. Remove and discard $68-\Omega$ resistor R116.
- R. Install electronic components assembly A1A2 (647-2781-001) onto the circuit card as shown in figure 1 using the existing hardware.
- S. Wind two turns of brown wire (422-0795-000) in transformer T3 as shown in figure 1, detail B. Connect to A1A2 assembly as shown in figure 1, detail D. If the transformer core has potting in the holes, carefully clear a way for the brown wire, using a stiff wire such as a straightened paper clip.
- T. Wind two turns of red wire (442-0796-000) in transformer T2 as shown in figure 1, detail D. If necessary, clear the core of potting as in step S.
 - NOTE: The added wires in steps S and T must be oriented as shown in figure 1, details B and C, to prevent oscillation.
- U. Reassemble the transceiver in the reverse order of disassembly.
- V. Mark SB 9 on the service bulletin information chart. If the transceiver does not have an information chart, install a chart (280-3778-010) near the nameplate.


MATERIAL INFORMATION


The parts listed below are required to modify one KWM-380 or one HF-380.


COLLINS PART NUMBER	$\overline{ ext{QTY}}$	$\frac{\text{UNIT}}{\text{PRICE}}$	DESCRIPTION
912-3315-000	1		Capacitor, 1000 pF, C55
240-2715-180	1		Coil, 2.7 μ H, L44
240-2029-000	2		Inductors, 3.3 μ H, L23, L24
745-1310-000	2		Resistor, 100 Ω , R123, R124
745-0683-000	1		Resistor, 15 Ω, R7
745-0692-000	1		Resistor, 27 \Omega, R7
421-2020-000	75 mm		Wire, #20 AWG, bus
	(3 in)		,
705-1075-000	ì		Resistor, $44.2 \text{ k}\Omega$, $R93$
647-2781-001	1		Assembly, electronic components, A1A2
422-0795-000	250 mm		Wire, A26TA00X1XXX
	(10 in)		,
422-0796-000	250 mm		Wire, A26TA00X2XXX
	(10 in)		,
*280-3778-010	ì		Chart, information
			•

^{*}Order if needed.




















POWER AMPLIFIER A4 (638-6775-001)



- RF PATH

Q2IA/Q2IB AND Q4IA/Q4IB ARE MATCHED PAIRS AND ARE MOUNTED ON POWER AMPLIFIER HEAT SINK. QI AND Q61 ARE MOUNTED ON POWER AMPLIFIER HEAT SINK.

634-6647